

| | | | | | | | | | | | |
|-------|------------|---------|-------|---|---|---|---|-----|-----------------|-----------|--|
| 19 | 8.5J | ET47 | HO | ○ | ○ | ○ | ○ | ○ | | 112 5H | 66.6 (57.1) |
| | 9.0J | ET25 | MO | | | | ○ | ○ | | | |
| | 9.0J | ET35 | HO | ○ | | ○ | ○ | ○ | | | |
| | 9.5J | ET45 | HO | ○ | ○ | ○ | ○ | ○ | | | |
| | 10.0J | ET30 | MO | | | | ○ | ○ | | | |
| 20 | 8.0J | ET27 | HO | | | ○ | | | | | |
| | 9.0J | ET25 | MO | ○ | ○ | ○ | ○ | ○ | | | |
| | | ET35 | HO | ○ | | ○ | ○ | ○ | | | |
| | 9.5J | ET35 | HO | | | ○ | | | | | |
| | | ET47 | HO | | | ○ | | | | | |
| 10.5J | ET35 | MO | ○ | ○ | ○ | ○ | ○ | | | | |
| 21 | 9.5J | ET30 | MO | | | | ○ | ○ | | | |
| | 10.5J | ET35 | MO | | | | ○ | ○ | | | |
| 22 | 10.5J | ET10 | LO | | | | ○ | ○ | Aidi Q8 | | |
| | | ET35 | MO | | | | ○ | ○ | BMW X5/X7 | | |
| | 11.5J | ET40 | LO | | | | ○ | ○ | BMW X5/X7 | | |
| 19 | 8.5J | ET30 | HO | ○ | | ○ | ○ | ○ | FF04/10/11 MO * | 120 5H | 72.6 (67.1) (66.9) (64.1) (60.1) |
| | 9.0J | ET20 | LO | | | ○ | | ○ | FF10/11 MO * | | |
| | | ET25 | MO | ○ | | | | | | | |
| | | ET44 | MO | | | ○ | | ○ | FF11 ET45 | | |
| | 9.5J | ET42 | MO | | | ○ | ○ | ○ | | | |
| | 10.0J | ET35 | LO | | | ○ | ○ | ○ | FF10/11 MO * | | |
| | | ET40 | MO | ○ | | | | | | | |
| 10.5J | ET26 | MO | ○ | | | | | | | | |
| 20 | 8.5J | ET30 | HO | ○ | | ○ | ○ | ○ | FF10/11 MO * | | |
| | 9.0J | ET25 | MO | ○ | ○ | ○ | | | | | |
| | 9.5J | ET20 | LO | | | ○ | ○ | ○ | | | |
| | | ET42 | MO | | | ○ | ○ | | | | |
| | 10.0J | ET40 | MO | ○ | ○ | ○ | | | | | |
| | | ET23 | LO | | | ○ | ○ | ○ | | | |
| | 10.5J | ET26 | MO | ○ | | ○ | | | FF04 LO * | | |
| ET35 | | MO | ○ | | | | | * | | | |
| 11.0J | ET43 | LO | | | ○ | ○ | ○ | | | | |
| 21 | 9.0J | ET30 | MO | | | | ○ | | | | |
| | 10.0J | ET40 | MO | | | | ○ | | | | |
| 22 | 10.5J | ET35 | MO | | | | ○ | ○ | Range Rover | 74.1 | |
| 20 | 8.5J | ET33 | HO | | | | ○ | ○ | 73.1 | 114.3 5H | 70.6 (66.1) (60.1) |
| | 9.0J | ET35 | MO | | | ○ | ○ | ○ | 73.1 | | |
| | 9.5J | ET35 | HO | ○ | | | | | | | |
| | 10.0J | ET35 | MO | | | ○ | ○ | ○ | | | |
| | | ET40 | MO | | ○ | ○ | ○ | ○ | FF15 HO / 73.1 | | |
| | 10.5J | ET45 | MO | ○ | | | | | | | |
| | 11.0J | ET50 | MO | | | ○ | ○ | ○ | FF04 LO | | |
| ET55 | | MO | | ○ | | | | | | | |
| 20 | 10.0J | ET20 | LO | | | | ○ | ○ | Dodge | 115 5H | 71.6 |
| 19 | 8.5J | ET45 | HO | | | ○ | | | | 108 5H | 63.4 |
| 22 | 9.5J | ET35 | MO | | | | ○ | ○ | Velar/XC90 | 63.4 | |
| 19/20 | 9.5J/11.0J | ET55/78 | HO/MO | | ○ | | | | | 120.65 5H | 70.3 |
| 19/20 | 9.0J/11.5J | ET45/52 | HO/MO | | | | ○ | | C8 | 120 5H | 66.9 |
| 19 | 8.5J | ET50 | HO | ○ | | | | | | 130 5H | 71.6 |
| | 10.0J | ET40 | MO | ○ | | | | | | | |
| | 11.0J | ET35 | MO | ○ | | | | | | | |
| ET60 | | MO | ○ | | | | | | | | |
| 20 | 8.5J | ET50 | HO | ○ | | | | | | | |
| | 9.0J | ET45 | HO | | | ○ | | ○ | 997/718 | | |
| | | ET50 | HO | | | | | ○ | | | |
| | 9.5J | ET55 | HO | | | ○ | | | | | |
| | 10.0J | ET40 | MO | ○ | | | | | | | |
| | | ET35 | MO | ○ | | | | | | | |
| | 11.0J | ET45 | LO | | | ○ | | | | | |
| ET50 | | MO | | | | | ○ | 718 | | | |
| ET60 | | MO | ○ | | | | | | | | |
| 11.5J | ET65 | MO | | | ○ | | | | | | |
| | ET45 | LO | | | | | ○ | | | | |
| ET65 | MO | | | | | ○ | | | | | |
| 20/21 | 9.0J/11.5J | ET45/58 | | | | | ○ | ○ | 992 | | |
| 22 | 10.0J | ET45 | MO | | | | ○ | ○ | Cayenne | 84.1 | |
| | 11.5J | ET50 | MO | | | | ○ | ○ | | | |
| | 10.5J | ET25 | MO | | | | ○ | ○ | G-Class AMG | | |
| | 10.5J | ET25 | LO | | | | ○ | ○ | G-Class *AMG NG | | |